
Gibraltar: Demolition by Neglect M. Melloy Photographs Page One



Gibraltar: Demolition by Neglect 23 November 2021 Page Two




2016 07 03 Pool House with old tarp, holes in the roof. Greenhouse with no roof.


Gibraltar: Demolition by Neglect 23 November 2021 Page Three




Gibraltar Mansion, Eastern Facade, August 2017



Gibraltar: Demolition by Neglect 23 November 2021 Page Fout




Gibraltar: Demolition by Neglect 23 November 2021 Page Five



Gibraltar: Demolition by Neglect 23 November 2021 Page Six




Gibraltar: Demolition by Neglect 23 November 2021 Page Seven





Gibraltar: Demolition by Neglect


23 November 2021 Page Eight




Gibraltar: Demolition by Neglect 23 November 2021 Page Nine



"A greenhouse/garage/service building, with laundry and living quarters for the chauffeurs were added to the pool house, by Pierson U-Bar Co. of New York City." Gibraltar National Register of Historic Places Nomination Form (1998), p. 8. 13 August 2021 Author Photographs "Gibraltar Preservation Group, LLC" providing a new definition of a Ggreenhouse.



Gibraltar: Demolition by Neglect 23 November 2021 Page Ten







Gibraltar: Demolition by Neglect 23 November 2021 Page Eleven

